


COUPP 60

Status report on DAQ Hardware, Software, and Integration

WBS 1.5


Peter Cooper, C. Eric Dahl, Dan Broemmelsiek,
Rick Kwarciany, Greg Deuerling

DAQ Modules



Linux box (LabView)

- Each module has corresponding LabView “virtual instrument”, that
 - Handles communication to physical module
 - Responds to notifiers from “Main”
 - (Re)Launch
 - Arm for Trigger
 - Report on Event
 - Module-specific commands
 - Expand (PLC), Manual Trigger (PLC), Enable Video Trigger (CTIC)
 - Writes data for each event
 - When idle, sends log info to “Main”




DAQ30I v1.vi

File Edit View Project Operate Tools Window Help

PLC Live View Last Trigger Fast Traces Run Setup Module Health

Live Images

0 Daff86 (cam 0) 12/07/2009 10:21:11.000



Camera I/O

- Frame Enable
- Video Trigger Enable
- Busy
- Trigger
- Integrate Enable
- Camera Ready
- Reserved
- Trigger Detected
- Trigger Latch
- LED Fault

Cam 0 Cam 1 Cam 2 Cam 3

CTIC I/O

- ENC_A
- ENC_B
- ENC_PB
- PB_D
- Local Mode
- Master / Slave
- PLC Compress

Manual Expand Begin Run

Manual Trigger End Run

Stop DAQ STOP

Compression/Expansion Time 3.211

Event Livetime 0

Run Livetime 65.456

Run Elapsed Time 2902.81

Frame Count 187 0 0 0

Skip Count 72 0 0 0

Cam 0 Cam 1 Cam 2 Cam 3

DAQ30I.lvproj/My Computer

12/08/2009

COUPP 60 Installation Readiness Review

Completion Status: PLC

- Hardware
 - Working in current state since spring
 - Building list of minor fixes for next run
 - Additional self-trigger condition
 - Changes to power-on state
 - Repair/remake cable to CTIC
- Software
 - Low-level (MODbus) code written and working
 - Virtual instrument written and working
 - Settings, event output, idle output defined and implemented
 - Need to tune piston position (compressed setpoint) to match pressure (expanded setpoint)

Completion Status: CTIC


- Hardware / Firmware
 - Operational unit completed Dec 3
 - Oct 1 - Firmware changes in CTIC requested (video trigger enable bit)
 - Nov 11-19, CTIC tested at D0, successfully triggered on bubbles and fanned signal to PLC, but full trigger fanout is missing
 - Nov 30, TTL output to Veto/Digitizers added, 0-24 V input from PLC added
 - Dec 2, frame-count and frame-skip-count fixed in firmware
 - Dec 3, 0-24 V input from PLC properly isolated
 - Dec 5, PLC <-> CTIC cable repaired

Completion Status: CTIC

- Software
 - Communication with module not robust, improved error handling necessary
 - Serial communication hang-up after 2 hour run
 - Virtual instrument written and working
 - Settings, event output, idle output defined and implemented

Completion Status: Cameras

- On-camera Software (operational Dec 4)
 - Multi-threaded Operation:
 - Main Thread
 - Receives settings from LabView via UDP
 - Updates settings in thread-safe manner
 - Starts/Stops imaging thread
 - Imaging Thread
 - Receives external triggers
 - Calculates video triggers
 - Communicates with CTIC (4bit TTL)
 - Writes images to NSF mounted disk
 - Operates up to 50 fps, more possible with reduced region-of-interest for trigger
 - Remaining issues
 - Late images for PLC triggers
 - Frame skipping
 - Synchronization of cameras untested at D0
 - Occasional failure to launch Imaging thread



Completion Status: Cameras

- LabView Software
 - Main camera threads launched by hand over telnet
 - Re-launching cameras from LabView not yet possible
 - Simultaneous read-write problem for live images (idle output)
 - Virtual instrument written and working
 - Settings, event output defined and (mostly) implemented

Completion Status: Veto

- Hardware / Firmware
 - Operational on 4kg chamber
 - Installed at D0
 - see Jeter's talk...
- Software
 - Low-level software written and working on 4kg chamber
 - Virtual instrument not yet written for COUPP60 DAQ

Completion Status: Digitizers

- Hardware
 - Limited to National Instruments boards supported on Scientific Linux
 - PXI-6115 (4 channels, 10 MHz per channel) in hand for Fast Digitizers
 - Less expensive options available on other platforms
 - Can run isolated Windows machine to manage digitizers
 - PXI-6221 (16 channels, 250 kHz total) in hand for Slow Digitizers

Completion Status: Digitizers

- Software
 - Low-level software provided by National Instruments
 - Tested on test-stand at FCC
 - Bugs in NI code found, corrected, reported
 - Fast digitizers (controlled memory access) working
 - Slow digitizers (DMA) working at rates below NI specifications, sufficient for our needs
 - Virtual instruments not yet written for COUPP60 DAQ

Summary

- On verge of long-term data taking
 - Remaining issue (CTIC serial) will be addressed this week
- Veto and digitizer virtual instruments needed
 - Operating bubble chamber not necessary to integrate these components
 - 1-2 post-doc weeks to finish
- Cannot further test video triggering on bubbles with current lighting
- Current D0 run can end next week, DAQ will be complete for next run