

EDR Review of uBoone RPS Findings Report
10.25.12

Hi Dave,

After looking at the chassis and the documentation of the RSP RevB:

- 1) As far as construction and wiring, all looks OK.
- 2) The fuse and fuse value should be indicated directly on the schematic. Currently it is just noted in the description document.
- 3) The voltage and current ratings for the auxiliary relay outputs should be labeled to prevent some "person" from using these contact to switch a DC voltage above 50 V or an AC line voltage.

So, I think it is OK to install this unit at Dzero.

Regards,
Steve